



PARTS LIST

Frame Stick



Accessory & Screw




Disk Kit

DK-A
X1




Cooler Kit


CK-A
X2




CK-B
X12



CK-C
X2



CK-H
X7





REAR VIEW
WITHOUT FAN

FRONT VIEW

Power Supply Kit

PK-L
X2




Please DO NOT remove the protect coat of frame sticks before you read this manual. The white label on each packing can help you distinguish the number of frame sticks.

MINERCASE V3 8-BAY


Installation Manual

www.veddha.com


OVERVIEW




STEP 1




STEP 2




STEP 3





STEP 4





STEP 5




STEP 6



STEP 7



STEP 8



STEP 9

