


PARTS LIST


Frame Stick




Disk Kit




Accessory & Screw



Cooler Kit



Power Supply Kit



REAR VIEW

WITHOUT FAN

FRONT VIEW


Please DO NOT remove the protect coat of frame sticks before you read this manual. The white label on each packing can help you distinguish the number of frame sticks.

MINERCASE V3 8-BAY


Installation Manual

www.veddha.com


OVERVIEW




STEP 1




STEP 2




STEP 3



STEP 4



STEP 5





MINERCASE V3 8-BAY



Installation Manual

www.veddha.com


STEP 6



STEP 7



STEP 8



STEP 9

